

2024 Mercedes Actros(EU) Test Reports

Tractor Information

EU/2024/Mercedes/Actros(EU)
VIN: W1T96342910799895
Sensor OE Part NO.: A0105429918

Odometer Reading: 0 km
License Plate: --

Trailer Information

EU/2024/Bendix/SmarTire Gold Series(EU)
Sensor OE Part NO.: K141468

License Plate:

Customer Information

Name: --



Tel: --

Device Information

Scanner: MaxiTPMS ITS600CV/V0.99.81

Serial Number: VT6GM3C01240

TPMS Comprehensive Test

Tractor Status&Repair advice	Trailer Status&Repair advice
 <p>Service & Repairs needed</p> <p><input type="checkbox"/> TPMS sensor replacement <input checked="" type="checkbox"/> Tire pressure adjustment <input checked="" type="checkbox"/> Tire replacement <input type="checkbox"/> Seasonal tire change</p> <p><input type="checkbox"/> Position relearn <input type="checkbox"/> Tire repair <input checked="" type="checkbox"/> Wheel alignment <input type="checkbox"/> Tire rotation</p> <p>Maintenance Suggestions:</p> <p>1. Adjust all tire pressures to placard:2L(O),3R(O) ; 2. Tire uneven wear detected,check if wheel alignment needed:3L(I), 3R(I) ;</p>	 <p>Service & Repairs needed</p> <p><input type="checkbox"/> TPMS sensor replacement <input checked="" type="checkbox"/> Tire pressure adjustment <input type="checkbox"/> Tire replacement <input type="checkbox"/> Seasonal tire change</p> <p><input type="checkbox"/> Position relearn <input type="checkbox"/> Tire repair <input type="checkbox"/> Wheel alignment <input type="checkbox"/> Tire rotation</p> <p>Maintenance Suggestions:</p> <p>1. Adjust all tire pressures to placard:1L,1R,2L,2R ;</p>

Tractor Tire Information (Note: The tread depth data comes from manual input.)

Location	Sensor ID information (Hex)			Sensor activation information				Tread Depth (mm)		
	CheckID	OBD ID	ID Status	Status	Battery	Pressure (kpa)	Temp. (°C)	Outside	Middle	Inside
1L	56000130	Unchecked	--	Pass	OK	936.0	27.0	4.0	4.0	4.0
1R	56A1D90D	Unchecked	--	Pass	OK	925.0	28.0	4.1	4.2	4.3
2L(O)	56000135	Unchecked	--	Pass	OK	603.0	28.0	1.0	2.5	2.4
2L(I)	56A1DB0E	Unchecked	--	Pass	OK	920.0	28.0	4.2	4.2	4.2
2R(I)	56000160	Unchecked	--	Pass	OK	914.0	29.0	4.1	4.1	4.1
2R(O)	56000137	Unchecked	--	Pass	OK	914.0	28.0	4.0	4.0	4.0
3L(O)	56000138	Unchecked	--	Pass	OK	925.0	28.0	3.9	3.9	3.9
3L(I)	56000113	Unchecked	--	Pass	OK	936.0	29.0	3.0	4.0	5.0
3R(I)	56000154	Unchecked	--	Pass	OK	920.0	28.0	5.0	4.0	3.0
3R(O)	56000117	Unchecked	--	Pass	OK	1161.0	28.0	4.4	4.2	4.3

Trailer Tire Information (Note: The tread depth data comes from manual input.)

Location	Sensor ID information (Hex)			Sensor activation information				Tread Depth (mm)		
	CheckID	OBD ID	ID Status	Status	Battery	Pressure (kpa)	Temp. (°C)	Outside	Middle	Inside

1L	00080107	Unchecked	--	Pass	OK	1.0	26.0	--	--	--
1R	00080144	Unchecked	--	Pass	OK	1.0	26.0	--	--	--
2L	00080131	Unchecked	--	Pass	OK	1.0	27.0	--	--	--
2R	00080159	Unchecked	--	Pass	OK	1.0	27.0	--	--	--

 **Tractor DTC Information (0 DTC)**

 **Trailer DTC Information (0 DTC)**

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.